


Linkage for Flanged MK Valves (MUT)

MOUNTING INSTRUCTIONS



- Mount the spindle extension on the valve stem tightening the dowel **(2)**;
- mount the linkage **(3)** on the valve and tighten the two M8 screws; **(4)** taking care to interpose the washers **(5)**;
- mount the nut **(6)** on the spindle extension **(1)**.